

FIG. 1





FIG. 2








FIG. 4A




FIG. 4B

	X	Y
No.1	$-L_x/3$	$L_y/3$
No.2	$-L_x/3$	0
No.3	$-L_x/3$	$-L_y/3$
No.4	0	$L_y/3$
No.5	0	0
No.6	0	$-L_y/3$
No.7	$L_x/3$	$L_y/3$
No.8	$L_x/3$	0
No.9	$L_x/3$	$-L_y/3$
No.10	$-9L_x/20$	$9L_y/20$
No.11	$-9L_x/20$	$-9L_y/20$
No.12	$9L_x/20$	$9L_y/20$
No.13	$9L_x/20$	$-9L_y/20$

FIG. 5A




FIG. 5B




FIG. 6A








FIG. 6B



204000" 95998007

FIG. 8








FIG. 10C




FIG. 10A




FIG. 10B

FIG. 11




FIG. 12C




FIG. 12A




FIG. 12D




FIG. 12B





FIG. 13



1006856 030402